










2012 RECOMMENDED DRIVER SWING SPEED










2012 RECOMMENDED DRIVER SWING SPEED





2012 RECOMMENDED DRIVER SWING SPEED





2012 RECOMMENDED DRIVER SWING SPEED

PROFORCE V2 IRONS														
Recommended Driver Swing Speed														
Model	50	55	60	65	70	75	80	85	90	95	100	105	110	115
PF V2 Constant Weight - 140									R			S		X

PROFORCE RV2 IRONS														
Recommended Driver Swing Speed														
Model	50	55	60	65	70	75	80	85	90	95	100	105	110	115
PF Rv2 75 Iron - 642						A			R			S		X
PF Rv2 95 Iron - 955									R			S		X
PF Rv2 115 Iron - 454									R			S		X

PROFORCE LADY IRONS													
Recommended Driver Swing Speed													
Model	50	55	60	65	70	75	80	85	90	95	100	105	110
PF V2 Lady Iron - 785L					L								

Recommended Driver Swing Speed													
Model	60	65	70	75	80	85	90	95	100	105	110		
UST 65 Gold					A			R			S		X

IROD															
Recommended Driver Swing Speed															
Model	60	65	70	75	80	85	90	95	100	105	110	115	120	125	130
IROD Driver - 7400					A			R			S		X		
IROD Hybrid .335 - 7500								R			S		X		
IROD Hybrid .370 - 780, 788								R			S		X		
IROD Transition Iron - 345								R			S		X		
IROD Transition Iron - 383								R			S		X		
IROD Tour Hybrid CB 90 - 790								R			S		X		
IROD Tour Hybrid CB 100 - 700								R			S		X		

MP SERIES													
Recommended Driver Swing Speed													
Model	50	55	60	65	70	75	80	85	90	95	100		
MP Woods - 4040, 4940					L			A			R		S
MP Irons - 386					L			A			R		S



2012 RECOMMENDED DRIVER SWING SPEED

